

PARTS LIST

No.	Description	Qty
1	Cross-head screw with left-hand thread	1
2	13mm metal ratchet drill chuck	1
3	Cross head screw	3
5	Torx self-tapping screw M4*13	4
4	Torque cup plastic lid	1
6	Torque cup	1
7	Gearbox	1
8	Speed control dial	1
9	Pull button wire	1
10	Motor teeth	1
11	Stator	1
12	Rotor	1
13	Lampshade	1
15	Forward	1
14	Lighting lamp	1
16	Switch	1
17	Control panel	1
18	Controller	1
19	Pin	1
20	Torx self-tapping screw M3*13	8
21	Handle decorative piece (left)	1
22	Chassis (left)	1
23	Decorative plug-in part (right)	1
24	Chassis (right)	1
25	Back cover	1
26	Torx self-tapping screw M3*13	4
27	Handle	1

ASSEMBLY DIAGRAM

