

PARTS LIST

No.	Description	Qty
1	Cross recessed screw M5*18	1
2	13mm metal wheel thread head	1
3	Counter sunk screw M5*8	1
4	Torque cup iron sheet	1
5	Torque cup	1
6	Torx self-tapping screw M3*13	4
7	Front fork decorative cover	1
8	Gearbox Assembly	1
9	Speed control gear shift	1
10	Speed control wire	1
11	Motor teeth	1
12	4812 Stator	1
13	4812 Rotor	1
26	Controller	1
25	Switch	1
23	Lighting lamp	1
14	Torx self-tapping screw M3*13	9
15	Crank handle decorative piece (right)	1
16	Right casing	1
17	Crank handle decorative piece (left)	1
18	Left casing	1
19	Rear rotary trim cover	1
20	Torx self-tapping screw M3*13	4
21	Forward	1
22	Lampshade	1
24	Control Panel	1
27	Switch pin	1

ASSEMBLY DIAGRAM

