PARTS LIST

No.	Description	Qty
1	Screw M5*18	1
2	Chuck 10mm	1
3	Right Housing	1
4	Screw ST3×14	11
5	Gearbox Assembly	1
6	Steel wire	1
7	Speed change button	1
8	Switch+LED Light	1
9	Reverse button	1
10	Motor teeth	1
11	Screw M3×6	2
12	Gearbox end cover	1
13	550 brush motor 20V	1
14	Left Housing	1
15	Right Buttom Housing	1
16	Plastic Cover	1
17	Plug Type	1
18	Left Buttom Housing	1

ASSEMBLY DIAGRAM

