

PARTS LIST

Part	Description	Qty
1	(Screws、gasket) assembly	1
2	Outer flange	1
3	Clamping flange	1
4	Elastic retainer for shaft37	1
5	Screws M4×8	1
6	Spanner for lower guard	1
7	Active Cover	1
8	Spring $\phi 3.8 \times 0.7 \times 98$	1
9	Plain washer $39 \times 43 \times 1.2$	1
10	Plastic sleeve	1
11	Screws M4×10	3
12	Output shaft	1
13	Front cover	1
14	Bearing 6001-2RS	1
15	Hole with elastic ring 28	1
16	Locating steel bushing	1
17	Half-Round key 3×10	1
18	Big gear	1
19	Elastic retainer for shaft 10	1
20	Bearing 8×14×8	1
21	Brand labeling	1
22	Screws M5×18	1
23	Washer	1
24	Elastic cylindrical pin 6×35	1
25	Cephalic shell	1
26	Bearing 6000-2RS	1
27	Spring $\phi 7.3 \times \phi 0.7 \times 33$	1
28	Self -pin	1
29	Rotor	1
30	Bearing 607-2RS	1
31	Bearing bushing	1
32	Wind proof circle	1
33	Screws ST4.2×55-F	2
34	Stator	1

Part	Description	Qty
35	Housing	1
36	Parameter labeling	1
37	Screws M5×35	1
38	Carbon brush	2
39	spring	2
40	Carbon brush holder	2
41	Screws ST2.9×8-F	4
42	Rear cover	1
43	Screws ST4.2×14-F	8
44	Screws M5×50	2
45	Left handle	1
46	Switch	1
47	Capacitor	1
48	Cable presser	1
49	Right handle	1
50	Cable jacket	1
51	Cable	1
52	Locking knob	1
53	Flat washer $\phi 6 \times \phi 14 \times 1.5$	2
54	Angle frame	1
55	nutM4	1
56	Screws M4×10	1
57	Bolt M6×14	1
58	riviter 5×7	2
59	Base	1
60	Screws M6×18	1
61	Depth frame	1
62	locking rob fordepth	1
63	Pressing knob	1
64	Spring $\phi 8.2 \times 0.8 \times 3$	1
65	Blade 185×20×2.4×24T	1
66	Parallel guide	1
67	Spanner 6	1

ASSEMBLY DIAGRAM

