


PARTS LIST(CORDLESS DRILL)

No.	Description	No.	Description
1	Inverted screw	11	Speed Button
2	chuck	12	Shell
3	Torque sleeve	13	Tapping Screw
4	Gearbox	14	Battery Pack
5	Motor Gear	15	Switch Assembly
6	Machine screw	16	Belt Clip
7	Motor	17	Machine screw
8	tuning fork	18	Magnet Ring
9	Handspike	19	Heat-shrink Tube
10	Variable Steel		

ASSEMBLY DIAGRAM(CORDLESS DRILL)



PARTS LIST(CORDLESS IMPACT WRENCH)

No.	Description	No.	Description
1	Tapping screw	12	Deep groove ball bearing
2	Rubber sleeve	13	Ring gear
3	Al head shell	14	Machine screw
4	Output shaft sleeve	15	Motor cover
5	Output shaft	16	Motor assembly
6	Movement assembly	17	Back shell
7	Gasket	18	Switch assembly
8	Impact component	19	Handspike
8_1	Impact block	20	Shell
8_2	Steel ball	21	Tapping screw
8_3	Gasket	22	Stents
8_4	Spring	23	Buffle
8_5	Central output shaft	24	Pcb
8_6	Steel ball	25	Battery pack
9	Planetary gear	26	Transparent cover
10	Gear pin	27	Belt clip
11	Gasket	28	Machine screw

ASSEMBLY DIAGRAM(CORDLESS IMPACT WRENCH)

