


### PARTS LIST



ASSEMBLY DIAGRAM

| No. | Description         | Qty | No. | Description          | Qty |
|-----|---------------------|-----|-----|----------------------|-----|
| 1   | Screw M5×18         | 1   | 10  | Gear                 | 1   |
| 2   | Chuck 10mm          | 1   | 11  | Screw M3×6           | 2   |
| 3   | Right Housing       | 1   | 12  | Gearbox end cover    | 1   |
| 4   | Screw ST3×14        | 11  | 13  | 550 brush motor 20V  | 1   |
| 5   | Gear Box Assay      | 1   | 14  | Left Housing         | 1   |
| 6   | Steel wire          | 1   | 15  | Right Buttom Housing | 1   |
| 7   | Speed change button | 1   | 16  | Makita Plug Type     | 1   |
| 8   | Switch+LED Light    | 1   | 17  | Left Buttom Housing  | 1   |
| 9   | Reverse button      | 1   |     |                      |     |