

PARTS LIST

No.	Description	Qty
1	Nozzle	1
2	Air duct	1
3	Diffusion bucket	1
4	Left and right handle	1
5	Button panel	1
6	Screw ST4 * 16	16
7	Rotary button	1
8	Button spring	1
9	Brushless motor	1
10	Case	1
11	Switch pin	1
12	Foot plate	1
13	Screw ST3 * 14	2
14	Platform adapter	1
15	Screw ST3 * 30	2
16	Shaft sleeve	1
17	Controller+light board	1
18	Whole fluid	1
19	Screw M4 * 12	4
20	Blade	1
21	Outer hexagonal flange bolt/M6 * 10	1
22	Intake hood	1

This exploded view diagram illustrates the assembly of a mechanical device, likely a handheld tool or a small motor. The components are numbered 1 through 22. The assembly sequence is as follows: 1. A long cylindrical housing (1) is shown at the top. 2. A shorter cylindrical component (2) is inserted into the housing. 3. A flange or cap (3) is attached to the end of component 2. 4. A small internal component (4) is shown below the flange. 5. A small rectangular component (5) is shown to the right. 6. A small circular component (6) is shown below component 4. 7. A small rectangular component (7) is shown below component 6. 8. A small circular component (8) is shown below component 7. 9. A small rectangular component (9) is shown below component 8. 10. A larger cylindrical component (10) is shown below component 9. 11. A small rectangular component (11) is shown below component 10. 12. A small rectangular component (12) is shown below component 11. 13. A small rectangular component (13) is shown below component 12. 14. A small rectangular component (14) is shown below component 13. 15. A small rectangular component (15) is shown below component 14. 16. A small rectangular component (16) is shown below component 15. 17. A small rectangular component (17) is shown below component 16. 18. A small rectangular component (18) is shown below component 17. 19. A small rectangular component (19) is shown below component 18. 20. A small rectangular component (20) is shown below component 19. 21. A small rectangular component (21) is shown below component 20. 22. A small rectangular component (22) is shown below component 21. The diagram uses dashed lines to indicate the alignment and assembly path of the components.