

PARTS LIST

Part No.	Description	Qty.	Part No.	Description	Qty.
1	Main housing	1	11	Valve spring	1
2	Valve seat	1	12	Air inlet	1
3	Valve plate	1	13	Bushing	1
4	End cap	1	14	O-ring	2
5	Piston	1	15	Air Regulator	1
6	Cylinder	1	16	Bolt	1
7	Spring retainer	1	17	Trigger	1
8	Chisel	4	18	Bolt	1
9	Valve stem	1	19	Soft grip	1
10	Valve	1			

Contact the distributor or sales agent from whom you purchase the tool for spare parts ordering for any necessary replacement to get continuous use of tool and for extending the tool life.
When ordering spare parts and components, give each part number and order quantity.

This exploded view diagram illustrates the assembly of a handheld power tool. The components are numbered as follows:

- 1**: Main housing or body of the tool.
- 2**: A circular component, likely a guard or cover, with a central opening.
- 3**: A small circular washer or spacer.
- 4**: A circular plate or disc with four mounting holes.
- 5**: A cylindrical component, possibly a motor or actuator.
- 6**: A long cylindrical shaft or tube with a threaded section.
- 7**: A coiled spring or cable.
- 8**: A long, thin, tapered component, possibly a blade or a long screw.
- 9**: A small cylindrical component.
- 10**: A small circular component.
- 11**: A coiled spring.
- 12**: A cylindrical component with a threaded end.
- 13**: A small cylindrical component.
- 14**: Two small circular components.
- 15**: A coiled spring.
- 16**: A long cylindrical component.
- 17**: A bracket or mounting plate.
- 18**: A small cylindrical component.
- 19**: A handheld device, possibly a control unit or a battery pack, with a keypad.