

PARTS LIST

NO.	Description	Qty	NO.	Description	Qty
1	Cord set	1	23	Nozzle	1
2	Sleeve	1	24	Spanner	1
3	Cord Fixing	1	25	Rivet	2
4	Screw	2	26	Steel sheet	1
5	Tigger	1	27	Rivet	2
6	Switch	1	28	Bobbin	1
7	Internal Wire	1	29	Rubber Sheet	1
8	Knob	1	30	E steel sheet	1
9	Shaft	1	31	Rivet	1
10	Rubber tip	1	32	Core clip	1
11	Base	1	33	Leaf spring	1
12	Spring Rivet	2	34	grip	1
13	Guard	1	35	Enclosure A	1
14	Rod	1	36	Shock absorber	4
15	Spring	1	37	Container holder	1
16	O ring	1	38	Suction tube	1
17	Cylinder	1	39	Container seal	1
18	O ring	1	40	Container	1
19	Hermetic end	1	41	Enclosure B	1
20	Spring	1	42	Label	2
21	Reek park	1	43	Screw	8
22	Spray sheet	1			

This exploded view diagram illustrates the assembly of a power tool, likely a drill or driver. The components are numbered 1 through 43. The main body (1) is shown at the bottom left, connected to a power cord (2). The trigger switch (3) and its button (4) are shown next to it. The motor housing (5) and its internal components (6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24) are shown in the center. The gear housing (25) and its internal components (26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43) are shown on the right. The diagram shows the relationship between the various parts, including the motor, gears, housing, and trigger switch.