

PARTS LIST

No.	Description	No.	Description
1	tapping screws	14	gasket
2	Spring gasket	15	Gear pin
3	Rubber sleeve	16	planet gear
4	circlip	17	ring gear
5	Quick change gasket	18	motor shaft gear
6	Quick change spring	19	deep groove ball bearing
7	Quick change sleeve	20	Motor
8	Al head shell	21	Back Cover
9	Output shaft sleeve	22	Handspike
10	Output shaft	23	Switch Assembly
11	Quick change of steel ball	24	Shell
12	gasket	25	Tapping Screw
13	Impact component	26	PCB stents assembly
13_1	impact block	27	Transparent Cover
13_2	steel ball	28	Battery pack (87257 not include)
13_3	gasket	29	Machine screw
13_4	spring	30	Belt clip
13_5	Central output shaft	31	Nameplate
13_6	steel ball		

ASSEMBLY DIAGRAM

