

PARTS LIST

No.	Description	Qty	No.	Description	Qty
1	Bolt	1	40	Big gear	1
2	Chip discharge hood	1	41	Front cover	1
3	Bolt with gasket	2	42	Ball bearing 6024	1
4	Scale block board	1	43	Spindle	1
5	Base assembly	1	44	Semicircle key	1
6	Foot	3	45	Pressing board	2
7	Bolt	3	46	Cutting disc	1
8	Screw assembly	1	47	Flange Washer	1
9	cotter pin	2	48	Bolt	1
10	Lastic cylindrical pin straight groove heavy	1	49	Bolt with gasket	4
11	Fast forward nut	1	50	Handle right cover	1
12	Seat for fast forward nut	1	51	Switch	1
13	Bolt with gasket	2	52	Handle left cover	1
14	Plain gasket	1	53	Bolt	6
15	Pin for vise	1	54	Wind block ring	1
16	Pressing board for vise	1	55	Ball bearing 6202	1
17	Plain gasket	1	56	Rotor assembly	1
18	Nut	1	57	Bolt	2
19	Dust cover	2	58	Stator assembly	1
20	Twister	1	59	Hous,ng	1
21	Large Spring	1	60	Bolt with gasket	4
22	Bolt	1	61	Carbon brush holder	2
23	Chain	1	62	Bolt	4
24	Plain gasket	1	63	Carbon brush	2
25	Nut	3	64	Brush holder coil spring	2
26	Bolt	1	65	Plain gasket	
27	Nut	2	66	Back cover	2
28	Bolt	1	67	Ball bearing 6000	1
29	Bolt	2	68	Bolt	3
30	Nut	2	69	Cable Sleeve	1
31	Main protection guard assembly	1	70	Bolt	2
32	Movable protection guard assembly	1	71	Pressing board for cable	1
33	Protective block	1	72	Cable	1
34	Chain fixing screw	1	73	Plain gasket	1
35	Self-lock pin	1	74	Spring gasket	1
36	Sping for self-lock pm	1	75	Bolt	2
37	Rocker arm	1	76	Protective lock nail	3
38	Ball bearing 629	1	77	Protective lock catch	3
39	External retaining ring	1			

ASSEMBLY DIAGRAM

